TOTAL SEE SEE SEEVENIS Approved or Release	e 2002/06/10 : CI	A-RDP69B26404	4R0001001300	074 <b>4</b> 3. 2405
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	and the constraint and the same of the sam		DSA 9	OYC
Driffs - V	SECRET	2	A THE THE PERSON AND A PROPERTY OF THE PERSON AND A PERSO	of E. The second
Soon Lampilla				and real course and a second real contraction of the second secon
ROUTING	ر المستقدم ا المستقدم المستقدم ال		A STATE OF THE STA	the control of the second seco
TO , MENTIACTIN	(MG)	6	The second secon	A Transcription of the Lead Spirite L
FROM: GV 177	,		To the second se	). If the second
ACTION:		The second secon	The second second of the secon	5
NO:		ু <sup>খ</sup> েইনকেন্ড	10.735	
25X1A	/		3	
IN 99381, Wender	TAN	osa 15 to		** ; ; **
SECRET 070507Z CITE	The second secon	and a section of the	CC	25X1A
FRIORITY				ZUNIA
OXCART				25X1A
GEN BACALIS FROM:	7		-	• • •

- 1. ON 127°S FLIGHT TODAY WE EXPERIENCED ANOTHER FAILURE WITH TYPE IG PACKAGE. CAMERA OPERATED FOR 50 SECONDS THEN FAILED. NUMEROUS ATTEMPTS TO RESTART ALSO FAILED. NO CHECKS HAVE BEEN MADE AS OF NOW OTHER THAN AN ELECTRICAL CHECK OF ATRCRAFT POWER TO PACKAGE; THIS WAS MADE PRIOR TO ENGINE SHUTDOWN AND WAS SATISFACTORY. CAMERA WOULD NOT OPERATE DURING THIS PERIOD.
- 2. WILL FLY 127 AGAIN TOMORROW WITH ANOTHER PACKAGE TO POSI-TIVELY ELIMINATE AIRCRAFT FACTOR. WILL ALSO REPLY PACKAGE G IN ARTICLE 129 TOMORROW IF PROBLEM DISCOVERED AND CORRECTED.
- 3. SPECIFICS WILL BE PROVIDED BY DCM AS SOON AS POSSIBLE.
  SECRET TOR: 070526Z SEP 67

SECRET

S SECTED

OSEA COCO CROULERS

ORICANODUROS SIGNI

COURTESSACROSCOSTO

COURTESSACROSCOS